

FIG. 1




FIG. 2A

AFTER N₂ ANNEALING




FIG. 2B

AFTER FGA+N₂ ANNEALING




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D




FIG. 10A




FIG. 10B




FIG. 10C




FIG. 11A




FIG. 11B




FIG. 12A




FIG. 12B




FIG. 13A




FIG. 13B




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18A

N₂ ANNEALING

PEELING




FIG. 18B

FGA+N₂ ANNEALING

